
Smoke and Dye Testing Summary

High Level Sewershed

| Run Summa | ry | | | | | | _ |
|-----------|----------------|-------------------|---------------------|-------------|---------------------|-----------------------|-----------------|
| Test ID | Test Type | Date Inspected | Company / Super. | Blower MH | Ground Condition | Notification Made? | Total Length |
| S1028-194 | Smoke | 7/27/2009 | ADS/TM | S17AA_033MH | Dry | Yes | 593.80 |



Smoke and Dye Testing Summary

High Level Sewershed

| Test ID | Test Type | Date Inspected | Company / Super. | Blower MH | Ground Condition | Notification Made? | Total Length |
|-----------|-----------|-------------------|---------------------|-------------|---------------------|-----------------------|-----------------|
| S1028-194 | Smoke | 7/27/2009 | ADS/TM | S17AA_033MH | Dry | Yes | 593.80 |

| lated Pipes —— | | | | |
|----------------|-------------|---------------|----------------|------------------|
| Pipe ID | Upstream MH | Downstream MH | Length (ft) | Diameter (In) |
| S17AA_041G1 | S17AA_041DE | S17AA_033MH | 93.9995 | 8 |
| S17AA_023G1 | S17AA_023MH | S17AA_033MH | 100.589 | 8 |
| S17AA_033G1 | S17AA_033MH | S17AA_032MH | 172.024 | 8 |
| S17AA_032G1 | S17AA_032MH | S15AA_011MH | 113.15 | 8 |
| S15AA_040G1 | S15AA_040MH | S15AA_011MH | 114.035 | 8 |
| | | | | |

Observations & Photos